



952 School Street #111
Napa, CA 94559
707-205-5706
mmichie@fitenvironmental.com

AHERA RE-INSPECTION

Woodside High School
199 Churchill Avenue
Woodside, CA 94062

Prepared for:

Sequoia Union High School District
480 James Ave
Redwood City, CA 94062

Project No.: 20-011
Date: February 18, 2020

Contents

EXECUTIVE SUMMARY 2

 RESPONSE ACTIONS 3

 1 PROJECT SUMMARY 4

 2 FIELD AND ANALYTICAL METHODOLOGY 4

 3 RECOMMENDATIONS..... 4

 4 ASSUMPTIONS AND LIMITATIONS 5

 5 SIGNATORY 5

Appendices

- Appendix A: Material Inventories
- Appendix B: F.I.T. Environmental Services Certifications

EXECUTIVE SUMMARY

F.I.T. Environmental Services (F.I.T. Services) conducted an AHERA re-inspection of Woodside High School, located at 199 Churchill Avenue Woodside, California. F.I.T. Services Certified Asbestos Consultants conducted the following activities to document the project:

- Visual inspection of known asbestos containing building materials (ACBM), both friable and non-friable.
- Identification of friable and non-friable ACBM.
- Assessment of friable and damaged non-friable ACBM.

All known asbestos containing building materials from the 2004 CTL Environmental Services AHERA 3-year re-Inspection that have not been removed, are in good condition and have been assigned a response action priority number of 8. See Appendix A.

RESPONSE ACTIONS

Response Action Priorities

- 1) Isolate area and restrict access. Immediate removal is mandatory; contact an Accredited Project Designer (APD).
- 2) Isolate area and restrict access. Repair or Remove Immediately; contact an APD. If ACBM remains following response action, follow up with O&M; restrict access to reduce disturbance potential.
- 3) Continue O&M. Limit access to reduce disturbance potential. Schedule repair or removal on a priority basis; contact an APD. If ACBM remains following response action, follow up with O&M; limit access to reduce disturbance potential.
- 4) Continue O&M. Limit access to reduce disturbance potential. Schedule repair or removal when practical and cost effective; contact an APD.
Continue O&M. Schedule repair or removal when practical and cost effective; contact an APD.
- 6) Same as 5 (lower priority basis).
- 7) Continue O&M. Reduce disturbance potential where practical. Remove when practical and cost effective; contact an APD.
- 8) Continue O&M until major renovation/demolition requires removal under NESHAPs or until hazard potential changes. Remove when practical and cost effective; contact an APD.

CLIENT: Sequoia Union High School District
480 James Ave.
Redwood City, CA 94062

ATTENTION: Walter Haub

REF.: AHERA Re-inspection
Woodside High School
199 Churchill Avenue
Woodside, CA 94062

1 PROJECT SUMMARY

F.I.T. Services conducted an AHERA re-inspection of Woodside High School, located at 199 Churchill Avenue Woodside, California. Patrick Garrett a certified Asbestos Consultant and EPA-accredited Building Inspector, conducted the inspection on February 18, 2020.

2 FIELD AND ANALYTICAL METHODOLOGY

The inspection was conducted in accordance with protocol set forth in the Asbestos Hazard Emergency Response Act (AHERA) *40 CFR 763 Subpart E*.

The re-inspection activities include the following elements:

- Visual inspection of known asbestos containing materials (ACM), both friable and non-friable.
- Identification of friable and non-friable ACM.
- Assessment of friable and damaged non-friable ACM.

3 RECOMMENDATIONS

During the inspection it was observed that new flooring had been installed throughout. Without documentation of abatement of original flooring, it is assumed that the original flooring was covered over with new floor tiles or carpet. ACM should be monitored and maintained as part of the Carlmont High School's operations and maintenance program until renovations or demolition activities require removal. Prior to removal or demolition activities these materials shall have samples collected by an EPA-accredited building inspector and analyzed via polarized light microscopy (PLM) in accordance with the method specified in appendix A Subpart F 40 CFR part 763, section 1. Remove or repair these materials when practical and cost effective in conjunction with an EPA-accredited Project Designer.

4 ASSUMPTIONS AND LIMITATIONS

This report was prepared exclusively for the use by Sequoia Union High School District and may not be relied upon by any other person or entity without F.I.T. Environmental Services express written permission. The information, conclusions, and recommendations described in this report apply to conditions existing at certain locations when services were performed and are intended only for the specific purpose, locations, time frames, and project parameters indicated. F.I.T. Environmental Services cannot be responsible for the impact of any changes in environmental standards, practices, or regulations after performance of services,

In performing our professional services, we have applied present engineering and scientific judgement and used a level of effort consistent with current standard of practice for similar types of studies.

As applicable, F.I.T. Environmental Services has relied in good faith upon representations and information furnished by individuals with respect to operations and existing property conditions, to the extent that they have not been contradicted by data obtained from other sources. Accordingly, F.I.T. Environmental Services accepts no responsibility for any deficiencies, omissions, misrepresentations, or fraudulent acts of persons interviewed.

F.I.T. Environmental Services will not accept any liability for loss, injury claim, or damage arising directly or indirectly from any use or reliance on this report. F.I.T. Services makes no warranty, expressed or implied.

This report is issued with the understanding that the client, the property owner, or its representative is responsible for ensuring that the information, conclusion, and recommendations contained herein are brought to the attention of the appropriate regulatory agencies, as required.

If you have any questions, please do not hesitate to contact the undersigned at 707-205-5706. We appreciate the opportunity to be of service to Sequoia Union High School District.

5 SIGNATORY

Respectfully Submitted by:

F.I.T. Environmental Services



Patrick Garrett, CAC (#15-5359)

Vice President, Principal Consultant

Reviewed by:

F.I.T. Environmental Services



Michael Michie, CAC (#11-4729)

President, Principal Consultant

Appendix A

Material Inventories



Client: Sequoia Union High School District
 Project No.: 20-011
 Project Name: AHERA re-inspection-Woodside High School
 Re-inspection: Patrick Garrett

Building A

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3)/ Percentage	Recommendations/ Response Action (4)
M	Vinyl Floor Tile & Mastic	Building B Rooms 1-12 & 15-18	ND	N	12,100 sf.	POS	8
M	Asbestos Cement Panels	Building B Below Windows	ND	N	9,000 sf.	POS	8
M	Vinyl Floor Tile & Mastic	Building C Rooms 1-2			2,400 sf.		Abated/Removed
M	Asbestos Cement Panels	Building C Rooms 1-2			2,000 sf.		Abated/Removed
M	Vinyl Floor Tile & Mastic	Building C Rooms 5-10, & 15-16	ND	N	15,400 sf.	POS	8
M	Asbestos Cement Panels	Building C Below Windows	ND	N	12,500 sf.	POS	8
M	9" Vinyl Floor Tile & Mastic	Building D MPR/Ground Floor	ND	N	2,300 sf.	POS	8
M	Vinyl Floor Tile & Mastic	Building E Rooms 1-18	ND	N	17,200 sf.	POS	8
M	Asbestos Cement Panels	Building E Below Windows	ND	N	18,200 sf.	POS	8
M	Asbestos Cement Panels	Building F Restrooms	ND	N	1,000 sf.	POS	8
M	Vinyl Floor Tile & Mastic	Building F Rooms 9-13	ND	N	6,400 sf.	POS	8
M	Asbestos Cement Panels	Building F Below Windows	ND	N	20,200 sf.	POS	8
M	Asbestos Cement Panels	Building G Below Windows	ND	N	7,000 sf.	POS	8

- (1) S: Surfacing, TSI: thermal system insulation, M: miscellaneous
 (2) ND: not damaged, D: damaged, SD: significantly damaged
 (3) POS: positive for asbestos, NEG: negative for asbestos, ASSUMED: not sampled, assumed asbestos containing.
 (4) For response actions 1-8 refer to "Response Action Ratings Sheet"

Appendix B

F.I.T. Services Certifications

Division of Occupational Safety and Health
Certified Asbestos Consultant

Patrick J Garrett

Name



Certification No. **15-5359**

Expires on **02/11/21**

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.

AHERA INSPECTION REPORT (1989)

SAMPLE / MATERIAL LOCATION DIAGRAMS

As part of the AHERA Asbestos Inspection the locations of samples collected are recorded on building diagrams. In addition to the sample locations, specific damage areas are recorded where found. The following pages provide the sample location diagrams for the School District. These drawings are organized in the same manner as the inspection/management plan data, i.e. campus one building one is first.

The title block contains the specific state, district, campus, and building or code with a 12 digit number. Next is the District Name, the Campus Name, and finally the Building Name. The next block provides the date the drawing was made, the street number, and finally the H-K drawing number.

The drawing uses several symbols and cross-hatching patterns to illustrate the key elements of the survey information.

SAMPLE LOCATION: The specific locations of samples are found on a point on the drawing leading to a symbol indicating the sample number and the Bulk Sample (BS) Code, which represents the type of material sampled. The Bulk Sample Code descriptions used are as follows:

BS CODE	DESCRIPTION	BS CODE	DESCRIPTION
0	Unknown	26	Transite Pipe
1	Acoustical Plaster	27	Transite Hood
2	Acoustical/Thermal Insul	28	Asbestos Pads
3	Hardwall/Ceiling Plaster	29	Asbestos Glove
4	Vinyl Floor Tile	30	Asbestos Rope
5	Pipe Covering	31	Raw Asbestos
6	Corrugated Pipe Covering	32	Electrical Wiring
7	Wrapped Paper Pipe Cover	33	Fire Hose
8	Boiler/Tank Insulation	34	Fire Door
9	Breeching/Exhaust Packing	35	Fire Suit
10	Woven Paper/Tape	36	Fire Brick
11	Drop or Lay-in Panel	37	Lab Counter Top
12	Acoustical Tile (1x1)	38	Fiber Frack Kiln
13	Fire or Stage Curtain	39	Tongs
14	MJP on Non-Suspect Pipe	40	Poured in Insulation
15	MJP on Pipe Covering	41	Contaminated Soil
16	MJP on Corr. Pipe Cover	42	Tectum
17	MJP on Wrapped Pipe Cover	43	Floor Underlayment
18	Fireproofing	44	Hard Grout
19	Vibration Joint Cloth	45	Mortar
20	Interior Duct Insulation	46	Blown or Scratch Coat
21	Exterior Duct Insulation	47	Oven/Autoclave Lining
22	Blown-in Insulation	48	Brake Lining
23	Stored Insulation	49	Theatre Curtain
24	Debris	50	Transite Siding
25	Gasket	99	Other

DAMAGE AREAS: When the inspector encounters a section of material in a Unified Sampling Area (USA) which contains localized damage in worse condition than the remainder of the same material contained in this USA, a Damage Area indicator is placed on the drawing. This symbol contains specific information about the damaged area.

Type of Material - The BS Code of the material is indicated so that the type of material can be determined. See the previous section for the listing of the BS codes used.

Quantity - The quantity of material which was found to be damaged is also indicated.

Location - The location of the localized damage is indicated in the symbol. This provides assistance in identifying where the damage can be found.

Response Action - This is the code for the recommended AHERA response action. The following codes are used:

1. Isolate Area Immediately
2. Gross Removal
3. Glove Bag Removal
4. Encapsulation
5. Enclosure
6. Repair and O&M
7. O&M and Monitor

CROSSHATCHING: Crosshatching patterns are used to detail the location of ceiling and floor material suspected of containing asbestos. There are three patterns used:

Floor Tile - This pattern is used to indicate floor tile and sheet flooring material suspected of containing asbestos.

Drop / Lay-in, Acoustical - This pattern is used to indicate the locations of a variety of ceiling tiles including, but not limited, to 1' x 1' and 2' x 4' lay-in panels.

Spray / Trowel Applied Materials - This pattern is used to indicate the presence of spray and trowel applied materials such as fireproofing and acoustical plaster.


LOCATION of CAUTION LABEL: The AHERA regulations require the use of labels indicating the presence of Asbestos Containing Building Material (ACBM). The label is to be placed on or near ACBM in routine maintenance areas in all school buildings. When this label is applied in the field the inspector identifies its location on the sample location diagram. On the drawing, the label symbol contains information about its placement within the routine maintenance area so that it may be readily found by the LEA. The label states the following.

CAUTION
ASBESTOS. HAZARDOUS.
DO NOT DISTURB
WITHOUT PROPER TRAINING
AND EQUIPMENT

The presence of sample numbers, crosshatching, and damage areas does not mean that all of the areas indicated contain asbestos. These location diagrams are a record of the field inspection only and are meant to show where samples were taken and what areas may be affected if asbestos is present. To determine which areas are affected, a review of the Inspection / Management Plan Data and the Petrographic Results contained in Sections 4 and 5 should be made. If desired, the location diagrams can be highlighted by the school district's asbestos coordinator to indicate the presence of asbestos containing material.





Location
of Caution
Label




Sample
Location

Bulk Sample
Description


Sample
or
Sample Range




Vinyl
Floor Tile



Drop,
Lay In,
Accoustical



Spray
Applied
Material



LEGEND:

VINYL FLOOR TILE

DROP LAY IN. ACOUSTICAL

SPRAY/TROWEL APPLIED MATERIAL


CAUTION BOILER ROOM ENTRANCE

BS01 00-02 SAMPLE LOCATION

BS CODE QUANTITY LOCATION DAMAGE AREA RESPONSE CODE

HALL-KIMBREL DAMAGE AREA SERVICES
440 WEST FIFTH STREET
LAWRENCE, KANSAS 66044
DATE 12/14/88 005001

AHERA COMPLIANCE PROGRAM
05-9018-005-001
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING B-1 TO B-4



LEGEND:



VINYL
FLOOR
TILE



DROP
LAY IN,
ACCOUSTICAL



SPRAY/TROWEL
APPLIED,
MATERIAL



LOCATION
OF CAUTION
LABEL



SAMPLE
LOCATION



DAMAGE
AREA

RESPONSE
CODE


— HALL-TORRELL
4440 WEST FIFTH STREET
LAWRENCE, KANSAS 66044

DATE
12/14/88


005002

— AHERA
COMPLIANCE PROGRAM

05-9018-005-002
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING B-5 TO B-8



LEGEND: VINYL FLOOR TILE DROP LAY IN ACCOUSTICAL SPRAY/TROWEL APPLIED MATERIAL		CAUTION BOILER ROOM ENTRANCE LOCATION OF CAUTION LABEL	SAMPLE LOCATION	DAMAGE AREA RESPONSE CODE	— HALL—KIDDELL 440 WEST FIFTH STREET LIVERMORE, CALIF. 94550 DATE 12/14/88	AREA COMPLIANCE PROGRAM 05-9018-005-003 SEQUOIA UNION SCHOOL DISTRICT WOODSIDE HIGH SCHOOL BUILDING B-11 TO B-12
--	--	--	--------------------	------------------------------------	--	--



BOILER ROOM

LEGEND:



VINYL
FLOOR
TILE



DROP
LAY IN,
ACOUSTICAL



SPRAY/TROWEL
APPLIED,
MATERIAL



CAUTION
BOILER ROOM
ENTRANCE



SAMPLE
LOCATION



DAMAGE
AREA

RESPONSE
CODE

— HALL-TURRELL

DATE


12/14/88

0050038

4340 WEST PETER STREET
DANBURG, MD 20804

AMER
COMPLIANCE PROGRAM

05-9018-005-003
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING B-11 TO B-12



LEGEND:



VINYL FLOOR TILE



DROP LAY IN, ACOUSTICAL



SPRAY/TROWEL APPLIED, MATERIAL



CAUTION BOILER ROOM ENTRANCE



LOCATION OF CAUTION LABEL



BS01 00-02 SAMPLE LOCATION



BS04 03 DAMAGE AREA




RESPONSE CODE

HALL-TORRELL
440 WEST FIFTEENTH STREET
LAURENS, KANSAS 66044

DATE 12/14/88
005004

HERA
COMPLIANCE PROGRAM

05-9018-005-004
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING B-13 TO B-16



LEGEND:

VINYL FLOOR TILE

DROP, LAY IN, ACCOUSTICAL

SPRAY/TROWEL APPLIED, MATERIAL

LOCATION OF CAUTION LABEL

SAMPLE LOCATION

DAMAGE AREA

RESPONSE CODE

HALL-TORRELL DESIGNATED SERVICE
 4240 WEST FIFTEENTH STREET
 LAWRENCE, KANSAS 66044
 DATE 12/14/88
 005005

AHERA COMPLIANCE PROGRAM
 05-9018-005-005
 SEQUOIA UNION SCHOOL DISTRICT
 WOODSIDE HIGH SCHOOL
 BUILDING B-17 TO B-18



	VINYL FLOOR TILE
	DROP; LAY IN ACOUSTICAL MATERIAL
	SPRAY/TROWEL APPLIED, MATERIAL

CAUTION
BOILER ROOM
ENTRANCE

LOCATION
OF CAUTION
LABEL



**SAMPLE
LOCATION**

Diagram illustrating the label structure:


BSCODE	QUANTITY
LOCATION	

RESPONSE CODE (indicated by a line pointing to a small circle on the label)

DAMAGE AREA

DATE	12/14/88	005006
HALL-MORRELL		
FEDERAL SERVICE		
4240 WEST FIFTEENTH STREET		
LAWRENCE, KANSAS 66044		

ALERA
COMPLIANCE PROGRAM
05-9018-005-006
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING C-1 TO C-2



LEGEND:

VINYL FLOOR TILE

DROP LAY IN, ACOUSTICAL

SPRAY/TROWEL APPLIED, MATERIAL

CAUTION
BOILER ROOM
ENTRANCE
LOCATION
OF CAUTION
LABEL

BS01
00-02
SAMPLE
LOCATION


BSCODE QUANTITY
LOCATION DAMAGE
AREA

RESPONSE
CODE

HALL-TOURNEL RESPONSE CODE
440 WEST PITCHER STREET
LURENCE, WISCONSIN 5304
DATE 12/14/88 005007

AHERA
COMPLIANCE PROGRAM
05-9018-005-007
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING C-5 TO C-8

BS04
14



LEGEND:



VINYL
FLOOR
TILE



DROP,
LAY IN,
ACoustical



SPRAY/TROWEL
APPLIED,
MATERIAL



LOCATION
OF CAUTION
LABEL



SAMPLE
LOCATION



DAMAGE
AREA




RESPONSE
CODE

— HALL-CORRELL —
400 WEST FIFTEETH STREET
LAUREL, KANSAS 66044

DATE
12/14/88

— HALL-CORRELL —
COMPLIANCE PROGRAM

05-9018-005-008
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING C-9 TO C-10



LEGEND:

VINYL
FLOOR
TILE

DROP,
LAY IN,
ACCOUSTICAL

SPRAY/TROWEL
APPLIED,
MATERIAL

CAUTION
BOILER ROOM
ENTRANCE
LOCATION
OF CAUTION
LABEL


BS01
00-02
SAMPLE
LOCATION

BSCODE QUANTITY
LOCATION DAMAGE
AREA

RESPONSE
CODE

DATE 12/14/88
005009

AREA
COMPLIANCE PROGRAM
05-9018-005-009
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING C-11 TO C-12



BS04 75%
THROUGHOUT 2

NOTE: THIS DAMAGE AREA
CODE APPLIES THROUGHOUT THE
BUILDING.



LEGEND:

VINYL
FLOOR
TILE

DROP;
LAY IN;
ACCOUSTICAL

SPRAY/TROWEL
APPLIED,
MATERIAL

CAUTION
BOILER ROOM
ENTRANCE
LOCATION
OF CAUTION
LABEL

BS01
00-02
SAMPLE
LOCATION



BSCODE QUANTITY
LOCATION DAMAGE
AREA

RESPONSE
CODE

— ELL-TORRELL
4840 WEST FIFTEENTH STREET
LAWRENCE, KANSAS 66044
DATE 12/14/88
005010

— AHRA
COMPLIANCE PROGRAM
05-9018-005-010
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING C-13 TO C-16

BS04
17



LEGEND:



VINYL
FLOOR
TILE



DROP-
IN
ACOUSTICAL




SPRAY/TROWEL
APPLIED
MATERIAL



CAUTION
LOCATION
OF CAUTION
LABEL



SAMPLE
LOCATION



DAMAGE
AREA





RESPONSE
CODE

— HALL-KIMWELL
440 WEST FIFTH STREET
LAWRENCE, MASS 01840
DATE 12/14/88
005011

AIHRA
COMPLIANCE PROGRAM
05-9018-005-011
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
D-ADMINISTRATION BUILDING

BS04
18



LEGEND:

VINYL FLOOR TILE

DROP, LAY IN, ACoustICAL

SPRAY/TROWEL APPLIED MATERIAL


CAUTION BOILER ROOM ENTRANCE
LOCATION OF CAUTION LABEL

BS01 00-02
SAMPLE LOCATION


BS04 QUANTITY LOCATION
DAMAGE AREA
RESPONSE CODE

HAU-JORRELL
440 WEST PITTSTOWN STREET
LAURENCE, KANSAS 66044
DATE 12/14/88
005013

ASHERA
COMPLIANCE PROGRAM
05-9018-005-013
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
D-LIBRARY BUILDING



LEGEND: VINYL FLOOR TILE DROP LAY IN. ACoustICAL SPRAY/TROWEL APPLIED MATERIAL		CAUTION BOILER ROOM ENTRANCE LOCATION OF CAUTION LABEL	BS01 00-02 SAMPLE LOCATION	BSCODE QUANTITY LOCATION * DAMAGE AREA	RESPONSE CODE	HAUL-TURRELL INTER-METAL SERVICE 4640 WEST FIFTH AVENUE LAWRENCE, KANSAS 66044 DATE 12/14/88 005015A	AHERA COMPLIANCE PROGRAM 05-9018-005-015 SEQUOIA UNION SCHOOL DISTRICT WOODSIDE HIGH SCHOOL MULTI-USE BUILDING
--	--	--	--	---	-------------------------	--	---








#1
BOILER ROOM



LEGEND: VINYL FLOOR TILE DROP LAY IN, ACOUSTICAL SPRAY/TROWEL APPLIED, MATERIAL		CAUTION BOILER ROOM ENTRANCE LOCATION OF CAUTION LABEL	BS01 00-02 SAMPLE LOCATION	BSCODE QUANTITY LOCATION DAMAGE AREA	RESPONSE CODE	HAZARD 4500 WEST PITCHER STREET LAWRENCE, MASS 01840 DATE 12/14/88 005015B	ANERA COMPLIANCE PROGRAM 05-9018-005-015 SEQUOIA UNION SCHOOL DISTRICT WOODSIDE HIGH SCHOOL MULTI-USE BUILDING
---	--	--	--------------------------------------	--	----------------------	---	---

BS04
28



LEGEND:



VINYL
FLOOR
TILE



DROP
LAY IN
ACCOUSTICAL



SPRAY/TROWEL
APPLIED
MATERIAL



CAUTION
BOILER ROOM
ENTRANCE



SAMPLE
LOCATION



DAMAGE
AREA




RESPONSE
CODE

— HALL THROUGH —
480 WEST PITCHER STREET
LAWRENCE, MASS 01840

DATE
12/14/88

ANERA
COMPLIANCE PROGRAM
05-9018-005-016
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING E-1 TO E-4



LEGEND:

VINYL
FLOOR
TILE

DROP
LAY IN
ACCOUSTICAL

SPRAY/TROWEL
APPLIED,
MATERIAL

CAUTION
BOILER ROOM
ENTRANCE
LOCATION
OF CAUTION
LABEL


BSO
60-02
SAMPLE
LOCATION

BSCODE QUANTITY
LOCATION
DAMAGE
AREA

RESPONSE
COOK

NAME: JAMES J. JAMES
440 WEST FIFTH STREET
LAWRENCE, MASS 01840
DATE 12/14/88
005017

ADHERA
COMPLIANCE PROGRAM
05-9018-005-017
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING E-5 TO E-8



LEGEND:

VINYL
FLOOR
TILE

DROP,
LAY IN,
ACCOUSTICAL

SPRAY/TROWEL
APPLIED,
MATERIAL

CAUTION
BOILER ROOM
ENTRANCE
LOCATION
OF CAUTION
LABEL

BS01
00-02
SAMPLE
LOCATION






BSCODE QUANTITY
LOCATION DAMAGE
AREA

RESPONSE
CODE

HALL-TROWEL
440 WEST FREDSON STREET
LAWRENCE, KANSAS 66044
DATE 12/14/88
005018

ASHER
COMPLIANCE PROGRAM
05-9018-005-018
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING E-9 TO E-12

BS04
31



LEGEND:



VINYL
FLOOR
TILE



DROP
LAY IN
ACCOUSTICAL



SPRAY/TROWEL
APPLIED
MATERIAL


CAUTION
BOILER ROOM
ENTRANCE
LOCATION
OF CAUTION
LABEL

BS01
00-02
SAMPLE
LOCATION


BSCODE QUANTITY
LOCATION
DAMAGE
AREA
RESPONSE
CODE

— BAIL-10000211
440 WEST FIFTH STREET
LAWRENCE, KANSAS 66044
DATE 12/14/88
005019

AREA
COMPLIANCE PROGRAM
05-9018-005-019
WOODSIDE SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
BUILDING E-13 TO E-16



LEGEND:		VINYL FLOOR TILE	DROP, LAY IN, ACoustICAL	SPRAY/TROWEL APPLIED, MATERIAL	CAUTION BOILER ROOM ENTRANCE LOCATION OF CAUTION LABEL	SAMPLE LOCATION	DAMAGE AREA	RESPONSE CODE	— HALL—TOWEL EMERGENCY EXIT 450 WEST FIFTH STREET LIVERMORE, CALIF 94550 DATE 12/14/88 005020	AHERA COMPLIANCE PROGRAM 05-9018-005-020 SEQUOIA UNION SCHOOL DISTRICT WOODSIDE HIGH SCHOOL BUILDING E-17 TO E-18
----------------	--	------------------	--------------------------	--------------------------------	--	-----------------	-------------	---------------	---	--



BS04
33

LEGEND:



VINYL
FLOOR
TILE



DROP
LAY IN
ACCOUSTICAL



SPRAY/TROWEL
APPLIED
MATERIAL



CAUTION
BOILER ROOM
ENTRANCE
LOCATION
OF CAUTION
LABEL



SAMPLE
LOCATION



DAMAGE
AREA

RESPONSE
CODE


— HALL—CORRIDOR—
6440 WEST FIFTH STREET
LAWRENCE, KANSAS 66044

DATE
12/14/88

005021


AFERA
COMPLIANCE PROGRAM

05-9018-005-021
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
WING F



LEGEND: VINYL FLOOR TILE DROP LAY IN. ACOUSTICAL SPRAY/TROWEL APPLIED MATERIAL		CAUTION BOILER ROOM ENTRANCE LOCATION OF CAUTION LABEL	SAMPLE LOCATION DAMAGE AREA RESPONSE CODE	HALL-KIMMEL 4340 WEST FIFTEENTH STREET LAWRENCE, KANSAS 66044 DATE 12/14/88 005023	AHRA COMPLIANCE PROGRAM 05-9018-005-023 SEQUOIA UNION SCHOOL DISTRICT WOODSIDE HIGH SCHOOL WING F
--	--	--	---	---	--

BS04
44



BS14
41-43

LEGEND:

VINYL
FLOOR
TILE

DROP
LAY IN
ACCOUSTICAL

SPRAY/TROWEL
APPLIED,
MATERIAL


CAUTION
BOILER ROOM
ENTRANCE
LOCATION
OF CAUTION
LABEL

BS01
00-02
SAMPLE
LOCATION

BSCODE QUANTITY
LOCATION
DAMAGE
AREA
RESPONSE
CODE


HAUL-YIMBELL
DANGER/HAZARD SERVICES
440 WEST FIFTH STREET
LAWRENCE, KANSAS 66044
DATE 12/14/88
005024A

AHERA
COMPLIANCE PROGRAM
05-9018-005-024
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
WING F



BOILER ROOM

LEGEND:		VINYL FLOOR TILE	DROP LAY IN. ACCOUSTICAL	SPRAY/TROWEL APPLIED MATERIAL	CAUTION BOILER ROOM ENTRANCE LOCATION OF CAUTION LABEL	BS01 00-02 SAMPLE LOCATION	ESCODE QUANTITY LOCATION DAMAGE AREA	RESPONSE CODE	HAU-DORREL 4240 WEST 17TH STREET LAWRENCE, KANSAS 66044 DATE 12/14/88	ASHERA COMPLIANCE PROGRAM 05-9018-005-024 SEQUOIA UNION SCHOOL DISTRICT WOODSIDE HIGH SCHOOL WING F - GYM AREA
----------------	--	------------------	--------------------------	-------------------------------	--	--------------------------------------	--	----------------------	---	---



LEGEND:

VINYL FLOOR TILE

DROP LAY IN, ACOUSTICAL

SPRAY/TROWEL APPLIED MATERIAL

CAUTION BOILER ROOM ENTRANCE

SAMPLE LOCATION

DAMAGE AREA

RESPONSE CODE

DATE 12/14/88

005025


ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED
DATE 05-01-2018 BY 60322
60322

05-9018-005-025
SECURIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
WING F

(

)

C



LEGEND:

VINYL FLOOR TILE

DROP LAY IN, ACOUSTICAL

SPRAY/TROWEL APPLIED MATERIAL

CAUTION BOLLER ROOM ENTRANCE LOCATION OF CAUTION LABEL

BS01 00-02 SAMPLE LOCATION

BSCODE QUANTITY LOCATION DAMAGE AREA


RESPONSE CODE

HALL-TROWELL
4240 WEST FIFTEENTH STREET
LAVERGNE, KANSAS 66044
DATE 12/14/88
005027

AHERA COMPLIANCE PROGRAM
05-9018-005-027
SEQUOIA UNION SCHOOL DISTRICT
WOODSIDE HIGH SCHOOL
WING "C"



LEGEND: _____  VINYL FLOOR TILE  DROP, LAY IN, ACoustICAL  SPRAY/TROWEL APPLIED, MATERIAL	 CAUTION BOILER ROOM ENTRANCE LOCATION LABEL	 SAMPLE LOCATION	 DAMAGE AREA	— PAUL TURRELL PERSONNEL SERVICES 4840 WEST 57TH STREET LAWRENCE, KANSAS 66044 DATE 12/14/88 005028	AHERA COMPLIANCE PROGRAM 05-9018-005-028 SEQUOIA UNION SCHOOL DISTRICT WOODSIDE HIGH SCHOOL WING G
--	---	---	---	---	---



BOILER ROOM

LEGEND:		VINYL FLOOR TILE	DROP LAY IN ACCOUSTICAL	SPRAY/TROWEL APPLIED MATERIAL	CAUTION BOILER ROOM ENTRANCE LOCATION OF CAUTION LABEL	SAMPLE LOCATION	DAMAGE AREA RESPONSE CODE	HALL-KIMBREL PARAMETER SERVICE 440 WEST FIFTH STREET LAWRENCE, KANSAS 66044 DATE 12/14/88 005029	AHERA COMPLIANCE PROGRAM 05-9018-005-029 SEQUOIA UNION SCHOOL DISTRICT WOODSIDE HIGH SCHOOL WING "C"
----------------	--	------------------	-------------------------	-------------------------------	--	-----------------	------------------------------	--	---